

Subject: Note 17_4INFO_9801024/25/26

We would like to inform you hereby that after 15th February 2017, as consequence of the replacement of motor codes reporting /TA version with the corresponding ones of /TN version (see Information 17_4INFO_TA_TN) the following products are changing as well: CB.16 Compressor, CB.25 Compressor and CB.40 Compressor.

The shift concerns the unification of each of these three Compressors with the corresponding Pump Codes. Therefore SB.16, SB.25 and SB.40 Vacuum Pumps will have the function of Compressor too. They will work as compressors thanks to the removal of the silencer from the Vacuum Pump as specified in the Operating and Maintenance Instructions (cod. 8702039 – 4.9.1).

You can find below a summary table of the above mentioned changes:

COMPRESSOR	COMPRESSOR CODE*	VACUUM PUMP	PUMP CODE (WORKING AS COMPRESSOR)
CB.16	97010024/MA	SB.16	9801024/MA
CB.16	97010024/TA	SB.16	9801024/TN
CB.25	97010025/MA	SB.25	9801025/MA
CB.25	97010025/TA	SB.25	9801025/TN
CB.25	97010025/MU	SB.25	9801025/MU
CB.40	97010026/MA	SB.40	9801026/MA
CB.40	97010026/TA	SB.40	9801026/TN

*The codes will be discontinued

We remain at your full disposal of any further information and clarification.

Subject to change without prior notice